# Installation

Base power cord entry PLUTOs are supplied as standard with the "clamp 80" kit for secure mounting to an 80mm grommet hole. For screw fixing Pluto can be ordered with just the bayonet mounting ring.

Side power cord entry PLUTOs are fitted with silicone rubber feet to provide grip and stability. Special brackets can be supplied to order for fitting the side power cord entry PLUTO to tool/equipment rails

PLUTO mounting adaptor ring screw fixing

Place mounting ring over 50-80mm* hole.
Screw mounting ring in place.

Align PLUTO with mounting ring as shown

mounting ring

Twist PLUTO into place until you hear a 'click'

*Miniumum 60mm hole is required for UK plug

PLUTO Clamp 80 Kit

Place mounting ring over 80mm hole. Place 80mm grommet into mounting ring and screw up retaining nut until firmly in place.

Align PLUTO with mounting ring as shown

80mm grommet

mounting ring

Retaining nut

Twist PLUTO into place until you hear a 'click'

Features

1. 140mm diameter hemisphere
2. Power socket outlet (up to 3)
3. Side exit for power cable only
4. Power socket can be substituted with USB
5. Power can exit via the base