

Zip Patch

Description: A fast-setting patch system for making permanent, waterproof field repairs.

Intended Use: Patching PVC/ABS piping, tanks, vessels, and containers. Repairing all substrates with a 1 hour functional cure.

Product Low odor technology Room temperature cure Non-sagging formula Bonds dissimular substrates Minimal surface preparation

Strong adhesion

Limitations:

Typical Physical Properties: Technical data should be considered representative or typical only and should not be used for specification purposes.

Cured 7 days @ 75° F

Adhesive Tensile Lap Shear (AL) 2,400 psi
AdhesiveTensile Lap Shear (ABS, PVC) 1,200 psi
Coefficient of thermal expansion 64 x 10(-5) in./in.[73°F to 194

Cured Shrinkage0.0010 in/inDielectric Strength250 volts/milsFlexural strength19,000 psiImpact Resistance30 ft.lbs./in.(2)

Peel Strength (GBS) 35 pli Pot Life 5 min 70 Shore D **Shore Hardness** Solids by Volume 100 **Tensile Elongation** 15-25% **Tensile Modulus** 192,000 psi **Tensile Strength** 10,000 psi Tpeel 35 pli

Uncured

Average thickness 1 ply: 0.075 in. Color **Brown** 4"x9" patch Coverage/Ib **Fixture Time** 1 hr. **Flashpoint** 300°F **Full Cure** 4 hrs. **Functional Cure** 1 hr. **Mixed Viscosity** 17,000 cps Service Temperature 200°F

TESTS CONDUCTED

Impact Resistance ASTM D 950
Tensile Strength (Epoxies) ASTM D 638
T-Peel Strength ASTM D 1876

Surface Preparation: Clean surface by solvent-wiping any deposits of heavy grease, oil, dirt, or other contaminants. Surface can also be cleaned with industrial cleaning equipment such as vapor phase degreasers or hot aqueous baths. If working with metal, abrade or roughen the surface to significantly increase the microscopic bond area and optimize the bond strength.

Mixing Instructions: Mixing is not applicable to this product. This is a primer system used to increase adhesion to your substrate. Follow instructions on the package for maximum results.

Application Instructions: Zip Patch requires minimal surface preparation. However, for maximum adhesion, the repair surface should be roughened and wiped clean with solvent. When making repairs to pipes, shut down the pressure. In tanks, pressure should be relieved by lowering the fluid level.

Apply only in well-ventilated areas. The Zip Patch kit contains everything required to make fast, permanent emergency

repairs. First, carefully peel away one side of the foil pouch. Then spray the exposed patch surface lightly, but completely, (including the corners) with activator. Proper activation is indicated by the patch becoming darker in color.

Press the activated patch over the repair area and carefully peel back the remaining foil. Use the plastic applicator provided in the kit to eliminate entrapped air by gently smoothing the patch from the center toward the outer edges. Complete activation of the adhesive by spraying the entire surface of the exposed patch.

Storage:

Store between 55°F and 75°F. Continuous storage above 75°F reduces the shelf life of the materials. Prolonged exposure above 100°F quickly diminishes the product's reactivity, and should be avoided. Shelf life can be extended by refrigeration between 45°F and 55°F. DO NOT FREEZE.

Compliances:

None

Chemical Resistance:

Chemical resistance is calculated with a 7 day, room temp. cure (30 days immersion) @ 75 °F)

Cutting Oil	Excellent
Gasoline (Unleaded)	Very good
Glycols/Antifreeze	Very good

Precautions:

Please refer to the appropriate material safety data sheet (MSDS) prior to using this product.

For technical assistance, please call 1-800-933-8266

FOR INDUSTRIAL USE ONLY

Warranty:

Devcon will replace any material found to be defective. Because the storage, handling and application of this material is beyond our control, we can accept no liability for the results obtained.

Disclaimer:

All information on this data sheet is based on laboratory testing and is not intended for design purposes. ITW Devcon makes no representations or warranties of any kind concerning this data.

Order Information:

11500 4" x 9" patch