Assembling Instruction

<u> </u>			
(1)Base	(2) Mechanism	A	С
X5		9 9 - (5) - 1 - (5) - 2	
(3)GasColumn	(4) Chair body		
(5)Screws			
		В	D
1. ① 2. ② 3. ①	X4 6X30MM X4 6X20MM X1 5MM		