



Heel Mark Disappearing Act

Z-Tread Spray Buff Solution

How do you make black heel marks vanish? With this ready-to-use spray that keeps maintenance down and your floor's appearance up. It eliminates the need for frequent floor stripping and refinishing by quickly restoring gloss and repairing scratch and scuff marks. This economical solution is great for spot burnishing and daily maintenance on high gloss finishes.

Benefits:

- Makes deep heel marks and scratches disappear
- · Restores gloss
- · Eliminates frequent refinishing
- Convenient-to-use spray

Applications:

- Schools
- Restaurants
- Airports
- Anywhere where hard floors need rejuvenating

Directions for Use:

Sweep or dust-mop floors to remove dust and dirt. If heavily soiled, clean with Neutral Floor Cleaner. Use red spray-buffing pad on any low or high-speed rotary floor machine. Lightly spray a small area of floor. Machine-buff until dry and glossy. Proceed to new floor area and repeat operation. Carefully control amount of spray. Excessive material will load pads and reduce efficiency.



Companion Products:

	Base Cod
Z-Tread Heavy-Duty Stripper	R031
Z-Tread Burnish Restorer	R038













Specifications:			
Physical Form	Thin, water-based liquid		
Color	Translucent, milky-white		
Odor	Mild		
рН	8.0 - 9.0		
Density - Specific Gravity	8.50 lbs./gal 1.008		
Flash Point (TCC)	150°F (66°C)		
Shelf Life	1 year minimum		
D.O.T. Shipping Label	None		



Packaging Information:

SKU	Package Quantity	Weight (lbs)	Length (")	Height (")	Width (")
R04201	12 quarts/case	27	13.25	10.63	11.25
R04224	4-1 gal/case	35	13.00	13.00	12.50

Safety:

Please make sure you have read and understand the product label and MSDS before using this product. MSDSs are available at www.zepprofessional.com. Put on appropriate personal protective



equipment. Store and use away from heat, sparks, open flame or any other ignition source. Avoid contact with eyes. Avoid prolonged or repeated contact with skin. Do not breathe vapor or mist. Do not ingest. Use only with adequate ventilation. Do not reuse container. Wash thoroughly after handling.

